

Lot No. 1289 PC120-8 88127

Check reports and descriptions serve only as a guide and do not guarantee an exhibit's performance, shape, or quality.

Basic Information

Job Status	Rental	Cabin/Canopy	Cabin	Cabin Type	ROPS
Front Attachment	Standard	Type of Shoe	Grouser	Width of Track Shoe	500
Bucket/Attachment	Standard BK	Others	Air Conditioner	Others	Multi Lever

Appearance

Under Covers	Deformed/Dent	Counter Weight	Scratched	Cabin	Deformed/Dent
--------------	---------------	----------------	-----------	-------	---------------

Front & Pins

Wear: Boom Foot Pin	Moderate/Within Service Limit	Wear: Boom/Arm Joint Pin	Moderate/Within Service Limit	Wear: Arm Tip Pin	Moderate/Within Service Limit
Wear: Other Pins	Moderate/Within Service Limit				

Undercarriage/Chassis/Tires

Wear: Track Link Tread(Right)	Moderate/Within Service Limit	Wear: Track Link Tread(Left)	Moderate/Within Service Limit	Wear: Track Link Pins & Bushings(Right)	Moderate/Within Service Limit
Wear: Track Link Pins & Bushings(Left)	Moderate/Within Service Limit	Wear: Track Shoe/Rubber Shoe	Moderate/Within Service Limit	Wear: Upper Rollers	Moderate/Within Service Limit
Wear: Lower Rollers	Moderate/Within Service Limit	Oil Leak: Rollers	1~4 Pieces	Wear: Front Idler(Right)	Moderate/Within Service Limit
Wear: Front Idler(Left)	Moderate/Within Service Limit	Wear: Sprocket(Right)	Moderate/Within Service Limit	Wear: Sprocket(Left)	Moderate/Within Service Limit

Overall Rating

Appearance Evaluation	Fair	Rust/Corrosion	Moderate
-----------------------	------	----------------	----------